

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER **Executive Director**

Division of Oil, Gas and Mining JOHN R. BAZA Division Director

Minerals Inspection Report

Report Date:

Reviewed W

Permit Number:	M/047/0007	Mine Status:	Active
Inspection Date:	03/21/2014	Permit Fees:	Paid
Inspection Time:	11:00 am	Bond Amount:	\$6,804,000
Weather:		Bond Escalation:	6/20/2015
Inspection Purpose: Review expansion area for Sage Grouse Habitat and Mitigation			
	Inspection Date: Inspection Time: Weather:	Inspection Date: 03/21/2014 Inspection Time: 11:00 am Weather:	Inspection Date: 03/21/2014 Permit Fees: Inspection Time: 11:00 am Bond Amount: Weather: Bond Escalation:

Conclusions and Recommendations

Elements of Inspection		Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds		
2.	Public Safety (shafts, adits, trash, signs, highwalls)		
3.	Protection of Drainages/Erosion Control		
4.	Deleterious Material		
5.	Roads (maintenance, surfacing, dust control, safety)		
6.	Reclamation		
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)		
8.	Soils		
9.	Revegetation		
10.	Other		

As per the State's Sage Grouse Initative Plan, We met on site to review the proposed expansion area, to determine if it really was sage grouse habitat, the level or type of use, and discuss mitigation measures that would be expected. Much of the expansion area has significant PJ which limits the use by the grouse. at least the area that will be mined for the first 4-5 years fall in this area. towards the northern boundary of the expansion area, it does open up and there is some potential for lek habitat but very limited nesting or brooding habitat. This area would likely be used more if scattered PJ trees were removed.

Mitigation was discussed on a 4:1 acre ratio (4 acres of mitigation for each 1 acre disturbed). Certainly the lower areas, once reclaimed would provide habitat and should be considered as part of the mitigation plan. The company has been participating in chaining projects off site (but adjacent to the mine) in the last couple of years. These areas would also be considered as part of the mitigation.

Inspector's Signature:

CC

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/Macs/Inspections/Inspection form 3.0.2 NewLG.pdf

